

# Inspection Photos

API: 05-009-06573

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 11/12/2019



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06573 | Date: 11/12/2019

## Inspection Photos



**Photo 1.** There is a two track access road that remains to the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06573 | Date: 11/12/2019



## Inspection Photos



**Photo 2.** Facing northeast toward the location. There is a bare are with no vegetation growth. Reclamation has not been performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06573 | Date: 11/12/2019

## Inspection Photos



**Photo 3.** There is a meter pipe riser that remains at the location. All equipment must be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06573 | Date: 11/12/2019



## Inspection Photos



**Photo 4.** Facing back toward the west at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06573 | Date: 11/12/2019

## Inspection Photos



**Photo 5.** View of bare are with no vegetation growth.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-06573 | Date: 11/12/2019