

Inspection Photos

API: 05-009-05117

Operator: TINDALL OPERATING COMPANY

Inspection Date: 11/12/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-009-05117 | Date: 11/12/2019

Inspection Photos



Photo 1. There is a two track access road that remains to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-05117 | Date: 11/12/2019

Inspection Photos



Photo 2. There is a shed and pipe risers that remain at the location. All equipment must be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-05117 | Date: 11/12/2019

Inspection Photos



Photo 3. There is no vegetation growth at this area of the location approximately 100 ft. x 60 ft. The location has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-05117 | Date: 11/12/2019

Inspection Photos



Photo 4. There is an area of subsidence near at the location approximately 8x8 ft.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-05117 | Date: 11/12/2019

Inspection Photos



Photo 5. Facing toward the back side of meter shed and pipe risers. All equipment must be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-05117 | Date: 11/12/2019