

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/15/2019

Submitted Date:

11/16/2019

Document Number:

696101568

**FIELD INSPECTION FORM**

Loc ID 330199 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	<a href="#">All Inspections</a>
,		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250805	WELL	SI	08/01/2019	OW	123-18608	MONFORT BB #30-13	PR

**General Comment:**

This is WELL inspection.  
Well(s): 1: Producing | PR.  
Battery: Active.

Centralized Battery serves 2 Location IDs (330198, 330199).  
(Well(s): 1: Producing | PR ; 1: Temporarily Abandoned | TA).

Refer to Field Inspection Report doc. #696101566 and/or Location ID #330198 for Battery / Facility, Equipment info.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type			
Comment:	Refer to Field Inspection Report doc. #696101566 and/or Location ID #330198 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		
			Date: _____
<b>Good Housekeeping:</b>			
Type			
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type			
Comment:	Refer to Field Inspection Report doc. #696101566 and/or Location ID #330198 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		

Corrective Action:		Date:	
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696101566 and/or Location ID #330198 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.368367,-104.488195
Comment:	Centralized Battery serves 2 Location IDs (330198, 330199). Refer to Field Inspection Report doc. #696101566 and/or Location ID #330198 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 250805 Type: WELL API Number: 123-18608 Status: SI Insp. Status: PR

**Producing Well**

Comment: [Producing | PR.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On FRI 11/15/2019 at approximately 16:15 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: NOBLE ENERGY INC                      Location Name: MONFORT-65N63W /30SWSW                      Location ID: 330199                      Well Name: Monfort BB 30-13                      API: 05-123-18608                      Location County: Weld County, Colorado                      Weather: Overcast &amp; Dry</p> <p>While there, I observed:                      Well(s): 1: Producing   PR.                      Battery: Active.</p> <p>Centralized Battery serves 2 Location IDs (330198, 330199).                      (Well(s): 1: Producing   PR ; 1: Temporarily Abandoned   TA).</p> <p>Refer to Field Inspection Report doc. #696101566 and/or Location ID #330198 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	11/16/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101569	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4990444">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4990444</a>