

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-07593
Date: 11-6-2019



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing here, largely with western wheatgrass and sand dropseed.



Photo 3. View of black pipes within the southwestern project area that need to be removed.



Photo 4. View of area on the well pad cut-slope where erosional rilling on bare soils and sedimentation are occurring, and stabilization measures are needed.



Photo 5. View of reference area west of the well pad, comprised of ponderosa pine forest with gambel oak understory.