

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/18/2019

Submitted Date:

11/18/2019

Document Number:

696101572**FIELD INSPECTION FORM**
 Loc ID 332785 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298998	WELL	PR	07/01/2019	OW	123-29229	SIEBRING 29PU	PR
299862	WELL	PR	07/01/2019	OW	123-29555	SIEBRING 33-29DU	PR

General Comment:

This is WELL inspection.
 Well(s): 2: Producing | PR.
 Battery: Active.

Centralized Battery serves 3 Location IDs (319202, 332785, 309676).
 (Well(s): 3: Producing | PR ; 1: Shut-In | SI).

Refer to Field Inspection Report doc. #696101570 and/or Location ID #319202
 for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type			
Comment:	Refer to Field Inspection Report doc. #696101570 and/or Location ID #319202 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	2: wellsites.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type			
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type			
Comment:	Refer to Field Inspection Report doc. #696101570 and/or Location ID #319202 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	2: wellsites. Iron panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type:	#		

Comment:	Refer to Field Inspection Report doc. #696101570 and/or Location ID #319202 for Battery / Facility, Equipment info.			
Corrective Action:			Date:	
Type: Bradenhead	# 2			
Comment:	2: wellsites. Appears plumbed to surface.			
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.368382,-104.456585	
Comment:	Centralized Battery serves 3 Location IDs (319202, 332785, 309676). Refer to Field Inspection Report doc. #696101570 and/or Location ID #319202 for Battery / Facility, Equipment info.					
Corrective Action:						Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	298998	Type:	WELL	API Number:	123-29229	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing PR.								
Corrective Action:						Date:			
Facility ID:	299862	Type:	WELL	API Number:	123-29555	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing PR.								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 11/18/2019 at approximately 12:31 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: PDC ENERGY INC Location Name: SIEBRING-65N63W /29SWSE Location ID: 332785 Well Names: Siebring 33-29DU, Siebring 29PU API: 05-123-29555, 05-123-29229 Location County: Weld County, Colorado Weather: Clear & Dry.</p> <p>While there, I observed: Well(s): 2: Producing PR. Battery: Active.</p> <p>Centralized Battery serves 3 Location IDs (319202, 332785, 309676). (Well(s): 3: Producing PR ; 1: Shut-In SI).</p> <p>Refer to Field Inspection Report doc. #696101570 and/or Location ID #319202 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	11/18/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101573	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4991134