

Inspection Photos
Operator: Catamount
Location/API #: 067-10021
Date: 11-12-2019



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with grasses such as western wheatgrass, crested wheatgrass, and blue grama.



Photo 3. View of erosional rilling within the southwestern cut-slope that is not stabilized.



Photo 4. View of reference area vegetation, comprised of pinyon juniper woodland with big sagebrush and gambel oak understory.