

Inspection Photos  
Location Name: Chevron-65S96W 596-31C Pad  
Location ID: #335999  
Inspection Date: November 14, 2019



Photo #1 – Facility sign.

Photo #2 – Corrected well signs (1).



Inspection Photos  
Location Name: Chevron-65S96W 596-31C Pad  
Location ID: #335999  
Inspection Date: November 14, 2019



Photo #3 - Corrected well signs (2).

Photo #4 - Corrected well signs (3).



## Inspection Photos

Location Name: Chevron-65S96W 596-31C Pad

Location ID: #335999

Inspection Date: November 14, 2019



Photo #5 - Corrected well signs (4).



Photo #6 – Hose with metal fitting in direct contact with tank battery liner (1).



## Inspection Photos

Location Name: Chevron-65S96W 596-31C Pad

Location ID: #335999

Inspection Date: November 14, 2019



Photo #7 - Hose with metal fitting in direct contact with tank battery liner (2).



Photo #8 – Metal bar and chain stored on top of tank battery liner.



## Inspection Photos

Location Name: Chevron-65S96W 596-31C Pad

Location ID: #335999

Inspection Date: November 14, 2019



**Photo #9 – Metal strip with nails stored on top of tank battery liner.**



**Photo #10 – Dark soil on north side of tank battery had hydrocarbon odor on inspection date.**

