

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/08/2019

Submitted Date:

11/12/2019

Document Number:

688306289

FIELD INSPECTION FORM

Loc ID 435180 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10706
Name of Operator: D90 ENERGY LLC
Address: 202 TRAVIS STREET #402
City: HOUSTON State: TX Zip: 77002

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 12 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Oakes, Kevin	713-227-0391	kevin@d90energy.com	Designated Agent
McCann, Randall	337-654-9804	rmccann@pcminc.com	Designated Agent
Silverman, Daniel	713-227-0391	dsilverman@d90energy.com	President

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435413	WELL	SI	06/01/2019	OW	073-06567	JOHN CRAIG 10-10	PR

General Comment:

Routine Inspection
Form 10 is in process, sending inspection to both operators until approved.

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	location sign at access road, AIRS permit and tank battery		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	303-638-6096	Date:	
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Prime Mover	# 1		
Comment:	gas engine		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	19 psi		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		

Comment:	cellar at wellhead has oil under metal grid, clean out cellar and fix leak		
Corrective Action:	"For localized stained soils or oily waste - ""Properly treat or dispose of oily waste in accordance with 907.e.""	Date:	11/26/2019

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Location Construction

Location ID: 435413 CDP: _____

Comment:

Corrective Action:

Date: _____

Form 2A COAs:

Comment: Form: (04) 401216149 04/27/2017 1) Venting or flaring of natural gas shall comply with COGCC Rule 912. 2) Submit requests to flare annually to COGCC on Form 4 (Sundry Notice), which discusses timing to connect to sales line, plans to develop infrastructure, and justification for continued venting/flaring. Provide gas analysis including H2S with each Sundry Notice. 3) Report flaring volumes on Form 7, Operator's Monthly Report of Operations. 4) The operator is required to obtain and maintain any required air permits from CDPHE. The combustion device must comply with applicable design destruction efficiency for hydrocarbons (typically enclosed device 98%). Document 401524230 04 -00 -VENT_FLARE-H2S is IN PROCESS on 02/13/2018.

Corrective Action: **Submit Form 4 for 2019 for review and approval to vent or flare.**

Date: **11/13/2019**

Wildlife BMPs:

Comment:

Corrective Action:

Date: _____

Comment:

Corrective Action:

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 435413 Type: WELL API Number: 073-06567 Status: SI Insp. Status: PR

Producing Well

Comment: [PR. Jun 2019 production last reported to COGCC database. Update Form 7s.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		

Comment: Two blue five gallon buckets at pumping unit engine are not in containment (see attached photo).

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402237198	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4986284
688306310	D90 Energy/KTM John Craig 10-10	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4986279