

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/08/2019

Submitted Date:

11/12/2019

Document Number:

693801242

**FIELD INSPECTION FORM**Loc ID 322348 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Graves, Jim	970-858-8550	mrinc20@qwestoffice.net	Operations Manager
Pesicka, Conor		conor.pesicka@state.co.us	
Ried, Jordan	970-563-4000	maralextechjr@gmail.com	All Inspections
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210336	WELL	SI	09/30/1986	GW	045-06092	BEAR GULCH-FEDERAL 30-4	TA

**General Comment:**

COGCC staff performed a followup field inspection on 11/8/2019. Followup to inspection doc#675203217 on 08/16/2016. Issues were found requiring corrective action. CA(s) from previous inspection not completed. See inspection text and photos for details. Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location			
<b>Lease Road:</b>			
Type	Main		
comment:	BLM		
Corrective Action	L	Date:	
Type	Access		
comment:	Private		
Corrective Action	L	Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Junk sign. Meter housing and dehydrator - disconnected. Flow line risers not LO/TO or marked are considered unused equipment. See photos for details		
Corrective Action:	Comply with Rule 603.f .		Date: 12/12/2019
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Pipe fence in disrepair		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Gas Meter Run	# 1		corrective date
Comment:	See unused equipment		
Corrective Action:			Date:
Type: Dehydrator	# 1		
Comment:	See unused equipment		
Corrective Action:			Date:



**Inspected Facilities**Facility ID: 210336 Type: WELL API Number: 045-06092 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well was found in state of Temporary Abandonment. TA status has not been approved via Form 4. Ongoing reporting via Form 7 has not been conducted. Well is overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 319.b. CA(s) from previous inspection not completed.

Corrective Action: Submit for Form 4 to request approval for TA status . Submit Form 7s and bring reporting up to date.  
Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 326 and 208.

Date: 12/12/2019

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402237674	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4986732">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4986732</a>
693801249	Inspection photos 11/8/2019	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4986728">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4986728</a>