

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/12/2019

Submitted Date:

11/12/2019

Document Number:

696300830**FIELD INSPECTION FORM**Loc ID 424175 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                   | Comment                         |
|--------------|-------|-------------------------|---------------------------------|
| Kraich, Adam |       | adam.kraich@state.co.us |                                 |
| James, Brian |       | bjames@hpres.com        | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 424173      | WELL | PR     | 08/29/2013  | OW         | 123-33925 | East Platte 1-01H | PR          |

**General Comment:**



**Location**Overall Good: ☒

|                      |  |       |            |
|----------------------|--|-------|------------|
| <b>Signs/Marker:</b> |  |       |            |
| Type                 | TANK LABELS/PLACARDS   |       |            |
| Comment:             | Middle Crude Oil tank - Content, NFPA label is peeling off. no longer legibel. See photo 3 |       |            |
| Corrective Action:   | Install sign to comply with Rule 210.d.  | Date: | 12/13/2019 |
| Type                 | WELLHEAD   |       |            |
| Comment:             | Adequate   |       |            |
| Corrective Action:   |  | Date: |            |
| Type                 | BATTERY  |       |            |
| Comment:             | Adequate   |       |            |
| Corrective Action:   |  | Date: |            |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | STORAGE OF SUPL  |       |            |
| Comment:           | Unmarked 2" riser at Wellhead, and unmarked 4" West of ECD |       |            |
| Corrective Action: | Comply with Rule 603.f .                                   | Date: | 11/14/2019 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                                   |     |       |                 |
|-----------------------------------|-----|-------|-----------------|
| <b>Equipment:</b>                 |     |       | corrective date |
| Type: VRT                         | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Bradenhead                  | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Gas Meter Run               | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Horizontal Heated Separator | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Emission Control Device     | # 1 |       |                 |



|                       |                        |       |  |
|-----------------------|------------------------|-------|--|
| Comment:              |                        |       |  |
| Corrective Action:    |                        | Date: |  |
| Type: Other           | # 1                    |       |  |
| Comment:              | Propane (1000 Gallons) |       |  |
| Corrective Action:    |                        | Date: |  |
| Type: Pump Jack       | # 1                    |       |  |
| Comment:              |                        |       |  |
| Corrective Action:    |                        | Date: |  |
| Type: Bird Protectors | # 5                    |       |  |
| Comment:              |                        |       |  |
| Corrective Action:    |                        | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER     | 1 | 400 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity                         | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------------------------------|---------------------|---------------------|-------------|
|                    |                                  |                     |                     |             |
| Comment:           | Shares berm with Crude Oil Tanks |                     |                     |             |
| Corrective Action: |                                  |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL          | 3 | 400 BBLS | STEEL AST |         | 40.349550,-104.168150 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         | Date:                 |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |



**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |



|                             |            |                       |            |                  |
|-----------------------------|------------|-----------------------|------------|------------------|
| <b>Inspected Facilities</b> |            |                       |            |                  |
| Facility ID: 424173         | Type: WELL | API Number: 123-33925 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>       |            |                       |            |                  |
| Comment:                    | PR         |                       |            |                  |
| Corrective Action:          |            |                       |            | Date:            |



**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <p><b>COGCC Inspection Report Summary</b></p> <p>On Thursday 11/07/2019 at approximately 11:36, I, Inspector Erica Petrie, conducted a Field Inspection at Highpoint Operating Corporation, East Platte 1-1H Location #424175 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unmarked 2" Riser at Wellhead and 4" west of ECD. Refer to Rule 603.f about unmarked Risers. See Photos 5 &amp; 6. Comply with Rule 603.f. Corrective Action date 11.14.2019</p> <p>Middle Crude Oil Tank - Content and NFPA label are fading, no longer legible, see photos3 &amp; 4. Comply with Rule 210.d. Corrective Action date 12.13.2019</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> <p>Continuing Educational Inspections</p> | petrie | 11/12/2019 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402236915    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4986061">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4986061</a> |
| 696300831    | Photos               | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4986055">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4986055</a> |