

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/18/2019

Submitted Date:

11/19/2019

Document Number:

696101580**FIELD INSPECTION FORM**Loc ID 331414 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261887	WELL	PA	06/12/2019	GW	123-20657	DOW 34-28	PA
447075	TANK BATTERY	AC	07/29/2016		-	DOW-65N63W 28SWSE	IO

General Comment:

This is a **PLUGGED & ABANDONED WELL & BATTERY** inspection.

Well(s): 1: Plugged & Abandoned | PA.

Battery: Abandoned | Dismantled. Most equipment removed.

Reclamation progressing.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Heated Separator	# 0		
Comment:	Abandoned Well & Battery.		
Corrective Action:		Date:	
Type: Emission Control Device	# 0		
Comment:	Abandoned Well & Battery.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	FIBERGLASS AST		,
Comment:	Battery in process of dismantling.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate

Comment: Shares berms w/ crude oil tank.							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	1	300 BBLS	STEEL AST		40.364987,-104.439754		
Comment: Battery in process of dismantling.							
Corrective Action:						Date:	

Paint

Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment: Shares berms w/ produced H2O tank.							
Corrective Action:					Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	261887	Type:	WELL	API Number:	123-20657	Status:	PA	Insp. Status:	PA
Workover									
Comment:		Plugged & Abandoned PA. Casing appears to be cut / capped. Form 6 doc. #402082983 indicates cut & cap date: 06/12/2019. Approved.							
Corrective Action:								Date:	
Facility ID:	447075	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	IO

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 11/18/2019 at approximately 15:42 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: DOW-65N63W /28SWSE Location ID: 331414 Well Name: DOW 34-28 API: 05-123-20657 Location County: Weld County, Colorado Weather: Overcast & Dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned Dismantled. Most equipment removed.. Reclamation progressing.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	11/19/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101581	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4992386