

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/19/2019

Submitted Date:

11/19/2019

Document Number:

697600594

**FIELD INSPECTION FORM**Loc ID 331755 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Anadarko		COGCCinspections@Anadarko.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
118604	PIT				-	CAMP D-1	EI
469221	SPILL OR RELEASE	AC	11/13/2019		-	Camp Federal 2-19A	EI

**General Comment:**

spill 469221 with active excavation underway by contractor crews. photo of ecavation attached

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: removed with equipment as production facility to be abandoned pre REM 13188

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: spill reporting up to date at time of inspection. Revised form 27 due within 45 days of spill discovery

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	118604	Type:	PIT	API Number:	-	Status:		Insp. Status:	EI
Facility ID:	469221	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PITType:  Lined:  Pit ID: 118604 Lat: 40.216786 Long: -104.816099Reference Point:  Other:  Length:  Width: **Lining:**Liner Type:  Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type:  Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type:  Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present:  Oil Accumulation:  2+ feet Freeboard: Comment: Corrective Action: Date: **COGCC Comments**

Comment	User	Date
pit 118604 at approximate location of spill 469221 and REM 13188, pit considered closed in 1995 as indicated in Amoco pit inventory submitted 12/21/1995 as document 2142990.	gintautp	11/19/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697600595	excavation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4992478">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4992478</a>