

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Ag fence		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Automation		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 282457 Type: WELL API Number: 123-23495 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 11/19/2019 at approximately 1240 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at the Swarts #1-6 Kerr McGee, at API #05-123-23495 in Weld County Colorado. While there, I observed PR wellsite. This is a follow up inspection per Doc. # 699300317 During this inspection the following compliance issue appears to have been addressed: Rule 204 Access Road: weeds not maintained along access road. see photo #1. Location photos attached. Location is dry, weather is clear/cloudy. No follow up on this site inspection needs to be conducted it appears that the compliance issue has been addressed to comply with COGCC Rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	11/19/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300614	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4992792