

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/19/2019

Submitted Date:

11/19/2019

Document Number:

696101586

FIELD INSPECTION FORM

Loc ID 331413 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

15 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------------|-------|----------------------------------|-----------------|
| Schlagenhauf, Mark | | mark.schlagenhauf@state.co.us | |
| MacLaren, Joe | | joe.maclaren@state.co.us | |
| , | | EHSRC@bonanzacrk.com | All Inspections |
| , | | dnr_cogccengineering@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 261886 | WELL | TA | 02/01/2018 | GW | 123-20656 | DOW 32-28 | PA |

General Comment:

This is a PLUGGED & ABANDONED WELL & BATTERY inspection.
Well(s): 1: Plugged & Abandoned | PA.
Battery: Abandoned. Most equipment removed.
Reclamation progressing.

Abandoned Battery SE corner GPS coordinates: 40.374897, -104.437971.

| Location | | | |
|--|---|--------|-------------------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Adequate | | |
| Corrective Action | L | | Date: |
| Overall Good: <input type="checkbox"/> | | | |
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |
| Good Housekeeping: | | | |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused equipment. a.) Gas meter runs at Abandoned Battery site. b.) 4: Deadman anchors at Plugged & Abandoned PA wellsite. Refer to Rule 603.f. See photos #2, 3. | | |
| Corrective Action: | Remove unused equipment. a.) Gas meter runs at Abandoned Battery site. b.) 4: Deadman anchors at Plugged & Abandoned PA wellsite. Comply w/ Rule 603.f. See photos #2, 3. | | Date: <u>12/20/2019</u> |
| Type | TRASH | | |
| Comment: | Junk (Cut casing pipe, well fence) at Plugged & Abandoned PA wellsite. Refer to Rule 603.f. See photo #4. | | |
| Corrective Action: | Remove Junk (Cut casing pipe, well fence) at Plugged & Abandoned PA wellsite. Comply w/ Rule 603.f. See photo #4. | | Date: <u>11/27/2019</u> |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Equipment: | | | |
| Type: Plunger Lift | # 0 | | corrective date |
| Comment: | Abandoned Well & Battery. | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 3 | | |
| Comment: | Remains at Abandoned Battery site. | | |
| Corrective Action: | | | Date: |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | Remains at Abandoned wellsite. | | |

| | | | |
|-----------------------------------|------------------------------------|-------|--|
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 0 | | |
| Comment: | Abandoned Well & Battery. | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 0 | | |
| Comment: | Abandoned Well & Battery. | | |
| Corrective Action: | | Date: | |
| Type: Pig Station | # 2 | | |
| Comment: | Remains at Abandoned Battery site. | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|---------------------------|----------|------|---------|--------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CRUDE OIL | 0 | | | | , | |
| Comment: | Abandoned Well & Battery. | | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | |
|------------------|--|--|
| Condition | | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | | |
|--------------------|---------------------------|---------------------|---------------------|-------------|--------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | Date: | | |
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 0 | | | | , | |
| Comment: | Abandoned Well & Battery. | | | | | |
| Corrective Action: | | | | Date: | | |

Paint

| | | |
|------------------|--|--|
| Condition | | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| |
|--|
| |
|--|

| Inspected Facilities | | | | | | | | | |
|----------------------|---|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 261886 | Type: | WELL | API Number: | 123-20656 | Status: | TA | Insp. Status: | PA |
| Workover | | | | | | | | | |
| Comment: | Plugged & Abandoned PA. Casing appears to be cut / capped. Form 6 doc. #402089957 indicates cut & cap date: 06/24/2019. Approval Pending. | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | | Gravel | | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary:</p> <p>On TUE 11/19/2019 at approximately 16:28 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: DOW-65N63W /28SWNE Location ID: 331413 Well Name: DOW 32-28 API: 05-123-20656 Location County: Weld County, Colorado Weather: Overcast & Dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. Most equipment removed. Reclamation progressing.</p> <p>Abandoned Battery SE corner GPS coordinates: 40.374897, -104.437971.</p> <p>During this inspection the following possible compliance issues were observed: 1.) Unused equipment. a.) Gas meter runs at Abandoned Battery site. b.) 4: Deadman anchors at Plugged & Abandoned PA wellsite. Refer to Rule 603.f. Remove unused equipment. a.) Gas meter runs at Abandoned Battery site. b.) 4: Deadman anchors at Plugged & Abandoned PA wellsite. Comply w/ Rule 603.f. Corrective Action date: 12/20/2019. See photos #2, 3.</p> <p>2.) Junk (Cut casing pipe, well fence) at Plugged & Abandoned PA wellsite. Refer to Rule 603.f. Remove Junk (Cut casing pipe, well fence) at Plugged & Abandoned PA wellsite. Comply w/ Rule 603.f. Corrective Action date: 11/27/2019. See photo #4.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p> | evinsb | 11/19/2019 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 696101587 | Site photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4992816 |