

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/07/2019

Submitted Date:

11/15/2019

Document Number:

689803319

**FIELD INSPECTION FORM**

Loc ID 416625 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10598  
Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC  
Address: 123 ROBERT S KERR AVE  
City: OKLAHOMA CITY State: OK Zip: 73102

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name         | Phone | Email                                      | Comment                         |
|----------------------|-------|--|---------------------------------|
| Inspections, General |       | sandridgeenvironmental@sandridgeenergy.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 298842      | WELL | PR     | 02/10/2017  | OW         | 057-06480 | Surprise 4-06H | PR          |
| 298844      | WELL | PR     | 11/20/2013  | OW         | 057-06482 | DAMFINO 2-06H  | PR          |

**General Comment:**

[Routine FIU inspection. All corrective actions from RIU inspection document number 692401287 remain.](#)

**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

| Type                            | #   |       | corrective date |
|---------------------------------|-----|-------|-----------------|
| Type: Bird Protectors           | #   |       |                 |
| Comment:                        |     |       |                 |
| Corrective Action:              |     | Date: |                 |
| Type: Emission Control Device   | # 2 |       |                 |
| Comment:                        |     |       |                 |
| Corrective Action:              |     | Date: |                 |
| Type: Horizontal Heater Treater | # 3 |       |                 |
| Comment:                        |     |       |                 |
| Corrective Action:              |     | Date: |                 |
| Type: Pump Jack                 | # 2 |       |                 |
| Comment:                        |     |       |                 |
| Corrective Action:              |     | Date: |                 |
| Type: Deadman # & Marked        | # 8 |       |                 |
| Comment:                        |     |       |                 |
| Corrective Action:              |     | Date: |                 |

**Tanks and Berms:**

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------|---|----------|------|---------|--------|
|          |   |          |      |         |        |

|                    |   |          |           |  |       |
|--------------------|---|----------|-----------|--|-------|
| PRODUCED WATER     | 3 | 400 BBLs | STEEL AST |  |       |
| Comment:           |   |          |           |  |       |
| Corrective Action: |   |          |           |  | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate |                     |                     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |
|                    |          | Date:               |                     |             |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL          | 6 | 400 BBLs | STEEL AST |         |        |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate |                     |                     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |
|                    |          | Date:               |                     |             |

**Venting:**

|                    |  |       |
|--------------------|--|-------|
| Yes/No             |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**

Facility ID: 298842 Type: WELL API Number: 057-06480 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 298844 Type: WELL API Number: 057-06482 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: [Rills in cut slope and evidence of sediment migrating onto location.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)  
[Comply with the 1003 interim reclamation rules.](#)

Date: 11/29/2019

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 689803320    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4993358">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4993358</a> |