

Inspection Photos
Location Name: Dry Creek Unit 3-22
Location ID: 316758



Photo 1. Overview of location taken facing east.

Inspection Photos
Location Name: Dry Creek Unit 3-22
Location ID: 316758



Photo 2. Stained soil at loadout valve.



Photo 3. Stained soil at loadout valve.



Inspection Photos
Location Name: Dry Creek Unit 3-22
Location ID: 316758



Photo 4. Depression with oily soil.



Photo 5. Close-up of oily soil in depression behind pump jack.

