

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/20/2019

Submitted Date:

11/20/2019

Document Number:

690101522

FIELD INSPECTION FORMLoc ID 331755 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Hamilton, Greg		Gregory.Hamilton@anadarko.com	
Gintautas, Peter		peter.gintautas@state.co.us	
		cogccinspections@anadarko.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265536	WELL	SI	01/01/2019	GW	123-21251	CAMP FEDERAL 2-19A	EG
469221	SPILL OR RELEASE	AC	11/13/2019		-	Camp Federal 2-19A	EG

General Comment:

Engineering Integrity inspection performed on November 18th, 2019 in response to initial form 19 spill report Doc #402236355 received by COGCC on 11/13/2019 that outlines: During plugging and abandonment activities at the Camp Federal 2-19A facility, historical petroleum hydrocarbon impacts were encountered beneath the partially buried produced water vessel.

Details of observations made during this field inspection are located in the flowline and comment sections of this report. Photos uploaded.

Inspected Facilities

Facility ID: <u>265536</u>	Type: <u>WELL</u>	API Number: <u>123-21251</u>	Status: <u>SI</u>	Insp. Status: <u>EG</u>
Facility ID: <u>469221</u>	Type: <u>SPILL OR</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EG</u>

Flowline

#1	Type:	of Lines
<u>Flowline Description</u>		
Flowline Type:	Size:	Material:
Variance:	Age:	Contents:
<u>Integrity Summary</u>		
Failures:	Spills:	Repairs Made:
Coatings:	H2S:	Cathodic Protection:
<u>Pressure Testing</u>		
Witnessed:	Test Result:	Charted:
<u>COGCC Rules(check all that apply)</u>		
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input checked="" type="checkbox"/> 1103. Abandonment		
<u>Comment:</u>	COGCC Inspector met with Anadarko contract personnel (P & P Services) on location. (1) Well (Camp Federal 2-19A) has been plugged and abandoned; COGCC form 42 notice of start of plugging operations Doc #402111984 received on 07/17/2019. (1) Well (Lewis C. Camp Unit D 1) was plugged and abandoned in May 2018. Contract personnel were completing excavation and remediation work at the time of this field inspection. Based on conversation with contract personnel, all flowlines (wellhead/ dump/ process) have been removed. No flowlines were observed in the open excavation on location. No flowline risers were observed during this field inspection at the (PA) wellhead or facility areas. Note: An existing Anadarko gas gathering pipeline has been marked (pin flagged) and runs off location from the meter run(s) (OOS) in a N-NE trending direction.	
Corrective Action:	Date:	

COGCC Comments

Comment	User	Date
*Note: There are (2) disconnected/ out of service gas gathering meter runs on the east side of location:	maclarej	11/20/2019
The following COGCC final reclamation rule(s) are applicable: COGCC Rule 1004. FINAL RECLAMATION OF WELL SITES AND ASSOCIATED PRODUCTION FACILITIES (partial description of rule) a. Well sites and associated production facilities. Upon the plugging and abandonment of a well, all pits, mouse and rat holes and cellars shall be backfilled. All debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well.		
As outlined in the corrective action section of the COGCC supplemental form 19: During plugging and abandonment activities at the Camp Federal 2-19A facility, historical petroleum hydrocarbon impacts were encountered beneath the partially buried produced water vessel. The Kerr-McGee tank battery facility will be deconstructed.	maclarej	11/20/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101523	Excavation and remediation in progress (view NE)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4993801
690101524	Out of service meter runs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4993802
690101525	Gas gathering Pipeline (marked/ pin flagged/ to NE)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4993803