

Inspection Photos  
Operator: Catamount Energy  
Location/API #: 067-08767  
Date: 11-12-2019



Photo 1. View of the project area from the well pad entrance facing center.





Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with dense rubber rabbitbrush and grasses such as smooth brome.





Photo 3. View from the beginning of the germination Transect 1, along the southern cut-slope, facing westward.





Photo 4. Birdseye view of vegetation in quadrat at the midpoint along the quadrat. Sparse desirable vegetation observed along the cut-slope. Common vegetation is largely annual weeds such as bird's beak and annual sunflower. Desirable seedlings observed appear to be largely Indian ricegrass and rubber rabbitbrush.





Photo 5. View of berms in the southern project area that are not stabilized and eroding. Vegetation on berms is largely annual weeds such as Russian thistle.



Photo 6. View of reference area vegetation, comprised of open sagebrush shrubland and open pinyon juniper woodland.