

Inspection Photos

Operator: Catamount Energy
Location/API #: 067-05279
Date: 11-12-2019



Photo 1. View of the project area from the southern edge facing center. Little desirable vegetation present in areas not in use for production.



Photo 2. View of the project area from the northeastern corner facing center.



Photo 3. View of the northern project showing areas that need revegetation around a small patch of perennial grass that is established.



Photo 6. View of reference area vegetation, comprised of open sagebrush shrubland and open pinyon juniper woodland.