

Inspection Photos
Location Name: CAYLEY 21-24
API#: 05-071-08804
INSP. #: 695101778



PHOTO 1: LOCATION




PHOTO 2: WELL SIGN

Inspection Photos
Location Name: CAYLEY 21-24
API#: 05-071-08804
INSP. #: 695101778



PHOTO 3: AREA OF IMPACTED SOIL BETWEEN PUMPJACK AND SOUND WALL. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 12-20-19



PHOTO 4: AREA OF IMPACTED SOIL AROUND WELLHEAD. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 12-20-19