

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/20/2019

Submitted Date:

11/21/2019

Document Number:

690101527

FIELD INSPECTION FORM

Loc ID 320135 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10602
Name of Operator: MCCLANE ENERGY INC
Address: 1412 103 RD AVE
City: NORTHGLENN State: CO Zip: 80260

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Whittington, Ellice		ellice.whittington@state.co.us	
MCCLANE, GENE		genemcclane@hotmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202786	WELL	PR	08/01/2016	OW	001-08191	VAN SCOYK 1	EG

General Comment:

COGCC Flowline Inspection Only. Photos Uploaded.
The Corrective Actions identified during this (EG) field inspection are located in the flowline section of this report.
Note: The corrective actions outlined on COGCC FIR Doc #693501663 submitted on 10/17/2019 are still applicable.
All CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Inspected Facilities

Facility ID: 202786 Type: WELL API Number: 001-08191 Status: PR Insp. Status: EG

Flowline

#1	Type: Non-Well Site	1 of Lines
----	---------------------	------------

Flowline Description

Flowline Type: Non-Well Site Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: The off location flowline (wellhead line) runs approximately 1980' southwest from the wellhead to battery. This off location flowline has not been registered with COGCC; Operator has not submitted COGCC Form 44.

Corrective Action: Operator shall comply with the following COGCC rule:

1101.a. Off-Location Flowline Registration.
 (1) An operator must register an off-location flowline constructed on or after May 1, 2018, by submitting a Flowline Report, Form 44, to the Director within 30 days after the flowline is placed into service. An off-location flowline in existence prior to May 1, 2018, must be registered by October 31, 2019. An off-location flowline registered as part of a produced water transfer system is not subject to this requirement.

Date: 10/31/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101533	Pump jack and signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4994467
690101534	View SW from wellhead to battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4994468
690101535	View NE from battery to wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4994469