

Inspection Photos

API: 05-071-07960

Operator: PRESCO INC

Inspection Date: 11/19/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 11/19/2019

Inspection Photos



Photo 1. There is an erosion channel head cut that has developed along the access road at Lat/Long:37.07589,-104.50931.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 11/19/2019

Inspection Photos



Photo 2. Facing southeast along the access road. The preexisting road was widened during operations. There is erosion along the side of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 11/19/2019

Inspection Photos



Photo 3. There is a deep erosion channel that has developed along the access road which has not been repaired. Arrow points to 3.5 ft. shovel to show depth of erosion gully. Lat/Long:37.07439,-104.50754



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 11/19/2019

Inspection Photos



Photo 4. Facing northeast along the access road. The pre-existing road was widened during operations. The side of the road is not stabilized and there is insufficient BMP's to prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 11/19/2019

Inspection Photos



Photo 5. There is erosion issues along the road which must be repaired. . The side of the road is not stabilized and there is insufficient BMP's to prevent erosion.
Lat/Long:37.07560,-104.50457



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 11/19/2019

Inspection Photos



Photo 6. There is erosion issues along the road which must be repaired. . The side of the road is not stabilized and there is insufficient BMP's to prevent erosion.
Lat/Long:37.07560,-104.50379



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 11/19/2019

Inspection Photos



Photo 7. There are numerous noxious weeds along the access road. (Musk thistle)
Noxious weed control was not performed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 11/19/2019

Inspection Photos



Photo 8. A culvert along the road has filled in with sediment and is not maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 11/19/2019

Inspection Photos



Photo 9. Facing southeast along the access road. The location is in the upper right side of the photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 11/19/2019

Inspection Photos



Photo 10. Facing southeast toward the location. A dry shallow pit remains at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 11/19/2019

Inspection Photos



Photo 11. There are noxious weeds present at the site. (Canada thistle, Musk thistle) Noxious weed control was not performed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 11/19/2019