

# Inspection Photos

API: 05-071-07969

Operator: PRESCO INC

Inspection Date: 11/19/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-071-07969 | Date: 11/19/2019

## Inspection Photos



**Photo 1.** There is an erosion channel head cut that has developed along the main access road at Lat/Long:37.07589,-104.50931.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 11/19/2019



## Inspection Photos



**Photo 2.** Facing southeast along the main access road. The preexisting road was widened during operations. There is erosion along the side of the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 11/19/2019



## Inspection Photos



**Photo 3.** There is a deep erosion channel that has developed along the road which has not been repaired. Arrow points to 3.5 ft. shovel to show depth of erosion gully. Lat/Long:37.07439,-104.50754



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 11/19/2019



## Inspection Photos



**Photo 4.** Facing northeast along the main access road. The pre-existing road was widened during operations. The side of the road is not stabilized and there is insufficient BMP's to prevent erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 11/19/2019



## Inspection Photos



**Photo 5.** There is erosion issues along the road which must be repaired. . The side of the road is not stabilized and there is insufficient BMP's to prevent erosion.  
Lat/Long:37.07560,-104.50457



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 11/19/2019



## Inspection Photos



**Photo 6.** There is erosion issues along the road which must be repaired. . The side of the road is not stabilized and there is insufficient BMP's to prevent erosion.  
Lat/Long:37.07560,-104.50379



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 11/19/2019



## Inspection Photos



**Photo 7.** There are numerous noxious weeds along the access road. (Musk thistle)  
Noxious weed control was not performed since previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 11/19/2019



## Inspection Photos



**Photo 8.** A culvert along the road has filled in with sediment and is not maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 11/19/2019



## Inspection Photos



**Photo 9.** Facing southeast along the access road to the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07969 | Date: 11/19/2019



## Inspection Photos



**Photo 10.** Facing northeast along the reclaimed portion of the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07969 | Date: 11/19/2019



## Inspection Photos



**Photo 11.** Facing northwest toward the location. There are numerous noxious weeds at the location (Musk thistle). Noxious weed control has not been performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07969 | Date: 11/19/2019



## Inspection Photos



**Photo 12.** Facing east toward the location. A shallow pit remains at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07969 | Date: 11/19/2019