

# Inspection Photos

11/07/2019

Operator: DIAMOND OIL & GAS INC - 10067

Location ID: 322500

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: DIAMOND OIL & GAS INC - 10067  
Location ID: 322500



**Photo 1:** Photo taken from the west end of the location, facing southeast. Photos 1-3 provide an overview of the location and reclamation in process from southeast, east to northeast. Location predominantly annual vegetation, though desirable perennial vegetative establishment evident.



Inspection Photos  
Operator Name: DIAMOND OIL & GAS INC - 10067  
Location ID: 322500



**Photo 2:** See comments under photo 1.





Inspection Photos  
Operator Name: DIAMOND OIL & GAS INC - 10067  
Location ID: 322500



**Photo 3:** See comments under photo 1.





Inspection Photos  
Operator Name: DIAMOND OIL & GAS INC - 10067  
Location ID: 322500



**Photo 4:** Photo taken from the access road, facing west. Vegetation on access road predominantly undesirable weedy plant species. Additional monitoring of reclamation on access road advised to determine if reclamation is progressing towards COGCC 1000 series standards.





Inspection Photos  
Operator Name: DIAMOND OIL & GAS INC - 10067  
Location ID: 322500



**Photo 5:** Photo taken from the access road, facing east. Photo shows areas of the access road where stormwater erosion degradation is becoming evident. Installation of additional BMPs is advised.



Inspection Photos  
Operator Name: DIAMOND OIL & GAS INC - 10067  
Location ID: 322500



**Photo 6:** Photo taken from the access road, facing north. Photo shows a low point in the access road where stormwater discharges into a drainage. Currently no BMPs appear to be in place to stabilize and protect drainage from stormwater runoff concentrated on access road. Head-cut and a gully will likely develop. Installation of additional BMPs is advised.



Inspection Photos  
Operator Name: DIAMOND OIL & GAS INC - 10067  
Location ID: 322500



**Photo 7:** Photo taken from the access road, facing west. Photo shows areas of the access road where stormwater erosion degradation is becoming evident. Installation of additional BMPs is advised.



Inspection Photos  
Operator Name: DIAMOND OIL & GAS INC - 10067  
Location ID: 322500



**Photo 8:** Photo taken from the access road, facing north. Photo shows vegetation over the reclamation area.

