

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/20/2019

Submitted Date:

11/21/2019

Document Number:

690101529

FIELD INSPECTION FORMLoc ID 414601 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10317

Name of Operator: PAINE* JOSEPH J.C. DBA PAINE PETROLEUM

Address: 3720 S LIPAN STREET

City: ENGLEWOOD State: CO Zip: 80110

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Whittington, Ellice		ellice.whittington@state.co.us	
		dnr_cogccenforcement@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Brian Qualls		tuv@mac.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
414619	WELL	SI	10/01/2017	OW	001-09718	JOSEPH J.C. PAINE NO. 1 ANADARKO	SI

General Comment:

COGCC Flowline Inspection Only. Photos Uploaded.

The Corrective Actions identified during this COGCC (EG) field inspection are located in the flowline section of report.

Note: The corrective actions outlined on COGCC FIR Doc #688402049 submitted on 04/30/2019 are still applicable.

ALL CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Inspected Facilities

Facility ID: 414619 Type: WELL API Number: 001-09718 Status: SI Insp. Status: SI

Flowline

#1	Type:	of Lines
----	-------	----------

Flowline Description

Flowline Type: _____ Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: This well is currently shut in.

The off location flowline (wellhead line) runs approximately 3250' S-SW from the wellhead to battery. This off location flowline has not been registered with COGCC; Operator has not submitted COGCC Form 44.

Corrective Action: Operator shall comply with the following COGCC rule:

1101.a. Off-Location Flowline Registration.

(1) An operator must register an off-location flowline constructed on or after May 1, 2018, by submitting a Flowline Report, Form 44, to the Director within 30 days after the flowline is placed into service. An off-location flowline in existence prior to May 1, 2018, must be registered by October 31, 2019. An off-location flowline registered as part of a produced water transfer system is not subject to this requirement.

Date: 10/31/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101537	Signage at pump jack	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4994823
690101538	View S-SW from wellhead to battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4994824
690101539	View N-NE from battery to wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4994825