

Inspection Photos  
Operator: Logos Operating  
Location/API #: 067-06249  
Date: 11-12-2019



Photo 1. View of the project area from the southeastern corner facing center.





Photo 2. View of the southern fill slope from the southeastern corner facing westward. Little desirable vegetative cover observed on the slope. Brown surface vegetation on slope appears to be field bindweed.





Photo 3. View of erosional rilling on well pad cut-slopes, need to be stabilized.





Photo 4. View of reference area comprised of sagebrush and pinyon juniper woodland.