

# Construction and Stormwater Inspection

November 19, 2019

Operator: EDGE ENERGY II LLC- #10671

Location ID: 456286

Inspection Document #: 697500866

Weld County, CO

NENE Section 29 T11N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Deporter /29-A Pad  
Location ID: 456286



**Photo 1.** Photo taken from the southern perimeter of location on 11/4/2019, facing East. Photo illustrates sediment accumulation within the shallow ditch BMP. Also, Operator shall stabilized the unconsolidated fill material along the southern location as this is susceptible to wind and water erosion.



**Photo 2.** Photo taken from the southern perimeter of location on 11/19/2019, facing East. Photo illustrates Operator increased the depth of the ditch and built a berm BMP. Also, Operator shall stabilized the unconsolidated fill material along the southern location as this is susceptible to wind and water erosion.



Inspection Photos  
Location Name: Deporter /29-A Pad  
Location ID: 456286



**Photo 3.** Photo taken from the western perimeter of location on 11/4/2019, facing South. Photo illustrates a shallow ditch BMP along the western location. This ditch BMP would not be considered installed to a sufficient depth.



**Photo 4.** Photo taken from the western perimeter of location on 11/19/2019, facing North. Photo illustrates Operator increased the depth of the ditch and built a berm BMP.



Inspection Photos  
Location Name: Deporter /29-A Pad  
Location ID: 456286



**Photo 5.** Photo taken from the southwestern perimeter of location on 11/4/2019, facing East. Photo illustrates what the Operator considered a sediment trap. Operator indicated that the depth below the riprap was ~24”.



**Photo 6.** Photo taken from the southwestern perimeter of location on 11/19/2019, facing East. Photo illustrates Operator increased the depth and size of the sediment trap.