

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/06/2019

Submitted Date:

11/21/2019

Document Number:

692401601

FIELD INSPECTION FORM

Loc ID: 467526 Inspector Name: Colby, Lou On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10598
 Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC
 Address: 123 ROBERT S KERR AVE
 City: OKLAHOMA CITY State: OK Zip: 73102

Findings:

7 Number of Comments
 0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		sandridgeenvironmental@sandridgeenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
467526	LOCATION	AC	09/14/2019		-	Spicer S32 Annex Pad	CI

General Comment:

This is a Construction and Stormwater Inspection. Form 42: NOTICE OF CONSTRUCTION: was Filed for this Site, Start Date 10/23/19. Conditions at time of Inspection were Clear Sunny Sky, breeze from the South at 42 degrees F. Elevation at Site is 8,130 ft.

Location Construction

Location ID: 467526 CDP: _____

Comment: Five pieces of heavy equipment and one bobcat were working at time of inspection, spreading base material on Pad & road and tracking/forming topsoil stockpile. Ditches are being used as perimeter controls with Silt fence back up.

Corrective Action: _____ **Date:** _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ **Date:** _____

Wildlife BMPs:

Comment: This Location is within a Sensitive Wildlife Habitat (Greater Sage Grouse).

Corrective Action: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
--------------	---------	------------	---------

WADDLES	Yes			
Comments: Erosion BMPs: Straw Bales				
Other BMPs:				
Corrective Action:				Date:
DITCHES	Yes			
Comments: Erosion BMPs: Perimeter control				
Other BMPs:				
Corrective Action:				Date:
BERMS	Yes			
Comments: Erosion BMPs:				
Other BMPs:				
Corrective Action:				Date:
SILT FENCES	Yes			
Comments: Erosion BMPs: perimeter control				
Other BMPs:				
Corrective Action:				Date:
SLOPE ROUGHENING	Yes			
Comments: Erosion BMPs:				
Other BMPs:				
Corrective Action:				Date:

Comment: Sufficient Stormwater controls are installed and functional.

Corrective Action: _____ **Date:** _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

--	--

Inspected Facilities

Facility ID: 467526 Type: LOCATION API Number: - Status: AC Insp. Status: CI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692401632	Inspection Photos CI	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995378