



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date: \_\_\_\_\_

**Equipment:**

corrective date

Type: Plunger Lift # 6

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Ancillary equipment # 8

Comment: Automation

Corrective Action:

Date: \_\_\_\_\_

Type: Bradenhead # 6

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Flaring:**

Type

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Inspected Facilities**

Facility ID: 434217 Type: WELL API Number: 123-38030 Status: PR Insp. Status: PR

Facility ID: 434218 Type: WELL API Number: 123-38031 Status: PR Insp. Status: PR

Facility ID: 434219 Type: WELL API Number: 123-38032 Status: PR Insp. Status: PR

Facility ID: 434220 Type: WELL API Number: 123-38033 Status: PR Insp. Status: PR

Facility ID: 434222 Type: WELL API Number: 123-38034 Status: PR Insp. Status: PR

Facility ID: 434223 Type: WELL API Number: 123-38035 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  | Material Handling And Spill Prevention | Pass                     |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment   | User    | Date       |
|---|---------|------------|
| At time of inspection location appears to be in compliance with COGCC rules.<br>At time of inspection perception of soil may have been distorted due to weather conditions. | medinaj | 11/21/2019 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 699500329    | pics        | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995499">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995499</a> |