

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/21/2019

Submitted Date:

11/21/2019

Document Number:

696300900**FIELD INSPECTION FORM**Loc ID 422842 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
James, Brian		bjames@hpres.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422836	WELL	PR	02/01/2018	OW	123-33406	Dutch Lake 17-25H	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Unmarked Risers at Pumping Unit and north of Gas Meter house, See photos 4 and 5		
Corrective Action:	Comply with Rule 603.f .	Date:	11/26/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused pipe on the Southside of location, see photo 6.		
Corrective Action:	Comply with Rule 603.f .	Date:	12/23/2019
Type	OTHER		
Comment:	Stained Soil at Wellhead, see photo 3		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	12/23/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: VRU	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electrical and Automation Equipment		
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:		Appears to be plumbed to surface		Date:	
Corrective Action:				Date:	
Type: Flare	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Gas Meter Run	# 2				
Comment:				Date:	
Corrective Action:				Date:	
Type: Emission Control Device	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Vertical Separator	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Bird Protectors	# 2				
Comment:				Date:	
Corrective Action:				Date:	
Type: Pump Jack	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 1				
Comment:				Date:	
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:		Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	500 BBLS	STEEL AST		40.464730,104.279210

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	422836	Type:	WELL	API Number:	123-33406	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 11/20/2019 at approximately 14:43, I, Inspector Erica Petrie, conducted a Field Inspection at Highpoint Operating Corporation, Dutch Lake 17-25, Location ID #422842 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused Piping on the Southside of Location, see photo 6. Comply with Rule 603.f. Corrective Action date 12.23.2019</p> <p>Unmarked 1" and 3" Risers at Pumping Unit and North of Gas Meter Houses. Refer to Rule 603.f about unmarked Risers. See Photos 4 and 5 . Comply with Rule 603.f. Corrective Action date 11.26.2019</p> <p>Stained Soil at Wellhead, see photo 3. Comply with Rule 907.e. Corrective Action date 12.23.2019</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> <p>Continuing Educational Inspections</p>	petrie	11/21/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696300901	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995570