

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Fiberglass Condensate Vault missing Capacity, see photo 4		
Corrective Action:	Comply with Rule 210.d.	Date:	12/23/2019
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused Chemical Tank south of Pumping Unit, see photo 3		
Corrective Action:	Comply with Rule 603.f .	Date:	12/23/2019
Type	OTHER		
Comment:	Unmarked Risers 1" at Pumping Unit and 3" by Separator, see photo 2 and 3		
Corrective Action:	Comply with Rule 603.f .	Date:	11/26/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused Tubing at Pumping Unit, see photos 5 and 6		
Corrective Action:	Comply with Rule 603.f .	Date:	12/23/2019

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			
Type: Flare	# 1		corrective date
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	TA'd Wellhead		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Propane Tank (1000 Gallons)		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to Surface		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment: Shares berm with Crude Oil Tanks		Date:			
Corrective Action:		Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	500 BBLs	STEEL AST		40.449530,-104.298070
Comment:		Date:			
Corrective Action:		Date:			
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:		Date:			
Corrective Action:		Date:			
Venting:					
Yes/No					
Comment:					
Corrective Action:	Date:				
Flaring:					
Type					
Comment:					
Corrective Action:	Date:				

Inspected Facilities

Facility ID: 423226 Type: WELL API Number: 123-33543 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 11/20/2019 at approximately 15:09, I, Inspector Erica Petrie, conducted a Field Inspection at Highpoint Operating Corporation, Dutch Lake 23-35, Location ID #423223 in Weld County, Colorado. While there, I observed Production Operations During this inspection the following possible compliance issues were observed: Unused Tubing at Pumping Unit, see photo 5 and 6. Comply with Rule 603.f. Corrective Action date 12.23.2019 Unmarked 1" at Pumping Unit and 3" Risers at Separator. Refer to Rule 603.f about unmarked Risers. See Photos 2 and 3 . Comply with Rule 603.f. Corrective Action date 11.26.2019 Unused Chemical Tank/Pump at Southside Pumping Unit, see photo 3. Comply with Rule 603.f. Corrective Action date 12.23.2019 Fiberglass Condensate vault missing Capacity, see photo 4. Comply with Rule 210.d. Corrective Action date 12.23.2019 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Continuing Educational Inspections</p>	petrie	11/21/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696300903	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995571