

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2019

Submitted Date:

11/15/2019

Document Number:

696300848**FIELD INSPECTION FORM**Loc ID 423230 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	
Kraich, Adam		adam.kraich@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
423234	WELL	SI	08/01/2019	OW	123-33545	Degenhart USX AE17-63HN	SI
423237	WELL	SI	08/01/2019	OW	123-33546	Degenhart State AE16-63HN	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained Soil in both Engine houses and north Exhaust, see photos		
Corrective Action:	Comply with Rule 603.f .	Date:	12/13/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Panel		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Panel		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 2	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 2	
Comment:	Appear to be plumbed to surface	
Corrective Action:		Date:
Type: Other	# 1	
Comment:	Propane (500 Gallons)	
Corrective Action:		Date:
Type: Pump Jack	# 2	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 3	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 2	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	100 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares berm with the Crude Oil Tanks				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	6	300 BBLS	STEEL AST		40.482440,-104.336890
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 423234 Type: WELL API Number: 123-33545 Status: SI Insp. Status: SI**Producing Well**Comment: Corrective Action: Date: **Idle Well**Purpose: ☒ Shut In☐ Temporarily AbandonedReminder: Comment: SICorrective Action: Date: Facility ID: 423237 Type: WELL API Number: 123-33546 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In☐ Temporarily AbandonedReminder: Comment: SICorrective Action: Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Friday 11/08/2019 at approximately 11:45, I, Inspector Erica Petrie, conducted a Field Inspection at Noble Energy INC, Degenhart State AE 16-63HN, at Location ID #423230 in Weld County, Colorado.</p> <p>Stained Soil at North exhaust and inside both Engine houses, see photos 3, 4, &amp; 5. Comply with Rule 603.f. Corrective Action date 12.13.2019</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> <p>Continuing Educational Inspections</p>	petrie	11/15/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402241216	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4990394">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4990394</a>
696300849	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4990390">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4990390</a>