

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2019

Submitted Date:

11/15/2019

Document Number:

699300587**FIELD INSPECTION FORM**Loc ID 318318 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesika, Conor		conor.pesicka@state.co.us	
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241098	WELL	PR	12/01/2017	OW	123-08886	SHELDON R. SICKLER 4	PR

General Comment:

Location				
Lease Road:				
Type	Access			
comment:	Weeds have been cut, Road is rutted			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Operator name has been updated but still has no emergent contact number			
Corrective Action:	Comply with Rule 210.b			Date: 10/19/2019
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	DEBRIS			
Comment:	Weeds have been cut along ROW but still all around PU,WH and Electric panel and transformers.They appear to have been sprayed.			
Corrective Action:	Comply with Rule 603.f			Date: 09/29/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	OTHER			
Comment:	Electric panel transformers and meter box- Steel pole			
Corrective Action:				Date:
Type	PUMP JACK			
Comment:	Fabricated angle iron			
Corrective Action:				Date:
Equipment:				
			corrective date	
Type: Pump Jack	# 1			
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 1			
Comment:				

Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel transformers and meter box		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Inspected Facilities

Facility ID: 241098 Type: WELL API Number: 123-08886 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 11/15/19 at approximately 1315 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at the Sheldon R. Sickler #4 KP Kauffman, at API #05-123-08886 in Weld County Colorado.</p> <p>While there, I observed a producing wellsite. This is a follow up inspection per Doc. # 699300214</p> <p>During this inspection the following possible compliance issue appears to have been addressed:</p> <p>603.f Housekeeping: Weeds overgrown on access rd. See photo 1.</p> <p>During this inspection the following possible compliance issues appear to have not been addressed:</p> <p>Rule 210.b Sign issue: Current sign on location has been updated with current operator information but has no emergency contact information. CA date 10/19/2019 see photo #2.</p> <p>603.f Housekeeping: Weeds overgrown on location appear to have been cut around ROW but remain lying on location and dead weeds all around PU, WH and electric panel area. Appear to have been sprayed see photos 3, 4, 5, 6, 7 and 8.</p> <p>Location is dry, weather is overcast.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	11/15/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402241206	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4990372
699300588	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4990371