

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/20/2019

Submitted Date:

11/22/2019

Document Number:

696101598**FIELD INSPECTION FORM**Loc ID 310065 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		EHSRC@bonanzacrk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295872	WELL	TA	09/01/2017	OW	123-25827	NORTH PLATTE 24-24	TA

**General Comment:**

This is a WELL inspection.

Well(s): 1: Temporarily Abandoned | TA.

Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs (310067, 310065).

(Well(s): 2: Temporarily Abandoned | TA).

Refer to Field Inspection Report doc. #696101596 and/or Location ID #310067  
for Battery / Facility, Equipment info.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:	Sign at access road to wellsite. Well NOT visible from sign. Consider posting an additional sign at wellsite similar to what is at other Bonanza Creek wells. See photos #1, 2.			
Corrective Action:				Date:
Type				
Comment:	Refer to Field Inspection Report doc. #696101596 and/or Location ID #310067 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:	Iron panel.			
Corrective Action:				Date:
Type				
Comment:	Refer to Field Inspection Report doc. #696101596 and/or Location ID #310067 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type:	#			corrective date
Comment:	Refer to Field Inspection Report doc. #696101596 and/or Location ID #310067 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	Appears plumbed to surface.			
Corrective Action:				Date:
Type: Other	# 1			

Comment: <a href="#">Wellhead: w/ Master &amp; casing valves.</a>			
Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.382849,-104.386612
Comment: <a href="#">Centralized Battery serves 2 Location IDs (310067, 310065). Refer to Field Inspection Report doc. #696101596 and/or Location ID #310067 for Battery / Facility, Equipment info.</a>					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	295872	Type:	WELL	API Number:	123-25827	Status:	TA	Insp. Status:	TA
Idle Well									
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: EQUIPMENT PRESENT/DISCONNECTED			
Comment:		<div>Temporarily Abandoned   TA. Observed well disconnected from flowline. Form 4 doc. #402074537 indicates TA: 08/08/2014. Approved. Form 21 Doc# 401106580 MIT done: 05/24/2016. Approved.</div>							
Corrective Action:							Date:		

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:  On WED 11/20/2019 at approximately 13:49 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC  Location Name: North Platte /24-24 Pad  Location ID: 310065  Well Name: North Platte 24-24  API: 05-123-25827  Location County: Weld County, Colorado  Weather: Overcast &amp; Dry.</p> <p>While there, I observed:  Well(s): 1: Temporarily Abandoned   TA.  Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (310067, 310065).  (Well(s): 2: Temporarily Abandoned   TA).</p> <p>Refer to Field Inspection Report doc. #696101596 and/or Location ID #310067 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	11/22/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101599	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995677">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995677</a>