

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	North West Tank - Missing Content and Capacity and NFPA label is peeling, see photo 2 South Tanks Missing Capacity and NFPA labels are peeling, see photo3		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 12/19/2019
Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Recycle Pump containment - Oily Waste and Wildlife protection devices not adequate. See Photo 4		
Corrective Action:	Install or repair wildlife protection equipment per Rule 324A.a Oily Waste - Properly treat or dispose of oily waste in accordance with 907.e.		Date: 12/19/2019
Type	OTHER		
Comment:	Stained Soil at both 2-Phase Separators		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.		Date: 12/19/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:			Date:
Equipment:			
Type: Vertical Heater Treater # 1			corrective date
Comment:			
Corrective Action:			Date:
Type: Vertical Separator # 1			
Comment:			
Corrective Action:			Date:
Type: Bird Protectors # 3			
Comment:			

Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares berm with Crude Oil Tanks				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	500 BBLs	STEEL AST		40.921410,-104.182720
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:	
Type	
Comment:	
Corrective Action:	Date:

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 11/14/2019 at approximately 13:21, I, Inspector Erica Petrie, conducted a Field Inspection at 8 North LLC, DF Ranch 15-12, Location ID #410059 in Weld County, Colorado. While there, I observed Production Operations During this inspection the following possible compliance issues were observed: Recycle Pump containment - Oily Waste and Wildlife protection devices not adequate. See photo 4. Install or repair wildlife protection equipment per Rule 324A.a Oily Waste - Properly treat or dispose of oily waste in accordance with 907.e. Corrective Action date 12.19.2019 North West Tank is missing Contents and Capacity, NFPA label is peeling. South Crude Oil Tanks are missing Capacity Labels and NFPA labels are peeling. See photos2 and 3. Comply with Rule 210.d. Corrective Action date 12.19.2019 Stained Soil at both 2-Phase Separators, see photo 5 and 6. Comply with Rule 907.e. Corrective Action date 12.19.2019 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Continuing Educational Inspections</p>	petrie	11/18/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402242500	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4991413
696300882	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4991406