

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			Date: _____
Corrective Action:			

Good Housekeeping:			
Type	OTHER		
Comment:	stained soil under crude oil tank valve		
Corrective Action:	Comply with Rule 907.e	Date:	10/31/2019
Type	DEBRIS		
Comment:	Dead weeds around electric panel and transformers.		
Corrective Action:	Comply with Rule 603.f	Date:	11/25/2019
Type	UNUSED EQUIPMENT		
Comment:	unused Meter box with electric wires exposed, old compressor in shed on location. unused flow line riser in Compressor shed.		
Corrective Action:	Comply with Rule 603.f	Date:	12/18/2019

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Steel pipe		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electric panel, transformers and meter box		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	50 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares containment with crude oil tank					
Corrective Action:				Date:	
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 240783 Type: WELL API Number: 123-08571 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 11/18/2019 at approximately 1530 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at the Meredith #2 KP Kauffman, at API #05-123-008571 in Weld County Colorado. While there, I observed a PR wellsite and Tank Battery. Follow up inspection per Doc. # 699300379 with updates due to added compliance issue. During this inspection the following possible compliance issues were observed: 603.f housekeeping: Dead weeds around electric panel & transformers and around old compressor house. CA date has been changed due to dead weeds around old compressor house. CA date 11/25/2019 See photo #7, 8 and 9. 603.f housekeeping: Unused meter box with exposed electric wire, old unused compressor . CA date has been changed due to addition of old compressor. CA date 12/18/2019 see photo #8 and 10. 907.e Spotty stained soil: stained soil under crude oil tank valve. Is now delinquent per Doc. # 699300379 CA date 10/31/2019 see photo #5. Location is dry, weather is cloudy. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	11/18/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402242627	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4991548
699300602	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4991544