

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/25/2019

Submitted Date:

11/25/2019

Document Number:

679601968**FIELD INSPECTION FORM**Loc ID 332759 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|----------------------------------|---------------------------------|
| , | | cogccinspection@pdce.com | All Inspections |
| , | | dnr_cogccengineering@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 260595 | WELL | SI | 11/01/2018 | GW | 123-20511 | SAUER 33-31D | PA |

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|--|--|------------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Disconnected/unused gas meter. See attached photo. | | |
| Corrective Action: | Comply with Rule 603.f. | | Date: 12/25/2019 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|------------------------|--|-------|
| Type | OTHER | | |
| Comment: | GAS METER HOUSE - wire | | |
| Corrective Action: | | | Date: |

Equipment:

| | | | |
|---------------------|-----|--|-----------------|
| Type: Gas Meter Run | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 260595 | Type: | WELL | API Number: | 123-20511 | Status: | SI | Insp. Status: | PA |
| Producing Well | | | | | | | | | |
| Comment: | PA; Form 6(S) DOC#: 402103425 (in process) in well file. | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | | Gravel | | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|---|----------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Monday, November 25, 2019 at approximately 12:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at SAUER 33-31D (PDC Energy), at API #: 05-123-20511 in WELD COUNTY Colorado.</p> <p>While there, I observed a plugged and abandoned wellhead.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. All production equipment has been removed from location EXCEPT the gas meter house. Please remove to COMPLY WITH RULE 603.F. (Corrective Action Date: December 25, 2019) See attached photo #2.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing Education Inspection.</p> | santistb | 11/25/2019 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 679601969 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4998205 |