

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/25/2019

Submitted Date:

11/25/2019

Document Number:

687905823**FIELD INSPECTION FORM**Loc ID 326677 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262346	WELL	SI	08/01/2019	GW	067-08677	FEDERAL 02-11 2	PR

**General Comment:**

Site inspection and equipment inventory with photos a the end of this report.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Maintained gravel access road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:	Sign posted at entrance to location.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Labels and placards posted on signs and on tank.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Contact information posted on signs.			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	SEPARATOR			
Comment:	Cattle panels around separator.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Gas Meter Run	# 1			corrective date
Comment:	Located in separator building.			
Corrective Action:				Date:
Type: Prime Mover	# 1			
Comment:	Electric VFD motor with MCC on pumping unit.			
Corrective Action:				Date:
Type: Vertical Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Flow Line	# 4			
Comment:	1-4" flowline from wellhead to separator. 1-2" flowline from separator dump valve to offsite produced water gathering system. 1-2" flowline from separator blowdown to produced water tank. 1-4" flowline from separator to offsite dogleg.			

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead with block valve assembly installed.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	PVC bradenhead access.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	PBV STEEL		,
Comment:	21 BBL tank.				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	262346	Type:	WELL	API Number:	067-08677	Status:	SI	Insp. Status:	PR
Producing Well									
Comment:	According to well file, Production shows as SI status since August/2019. At time of inspection, pumping unit is online and producing.								
Corrective Action:								Date:	

--	--	--	--	--	--	--	--	--	--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gradient Terraces	Pass					
Ditches	Pass	Gravel	Pass			
Gravel	Pass					
Berms	Pass	Culverts	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905824	Overview photo looking South.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4998210">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4998210</a>