

Inspection Photos
Location Name: Waste Management #2L-441
Location ID: 432119



Photo 1 WH sign

Photo 2 wellsite

Inspection Photos
Location Name: Waste Management #2L-441
Location ID: 432119



Photo 3 TB signs

Photo 4 TB

Inspection Photos
Location Name: Waste Management #2L-441
Location ID: 432119



Photo 5 no containment under aux. tank

Photo 6 stained soil removed exhaust has been rerouted

Inspection Photos
Location Name: Waste Management #2L-441
Location ID: 432119



Photo 7

Photo 8 stained soil removed mech. Issue appears to have been addressed

Inspection Photos
Location Name: Waste Management #2L-441
Location ID: 432119



Photo 9 unused drums no containment

Photo 10 heated horiz.sep.

Inspection Photos
Location Name: Waste Management #2L-441
Location ID: 432119



Photo 11 ECDs

Photo 12 Gas meter run