

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/25/2019

Submitted Date:

11/25/2019

Document Number:

699300631**FIELD INSPECTION FORM**Loc ID 317489 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**14 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Leonard, Mike		mike.leonard@state.co.us	
,		dnr_cogccengineering@state.co.us	
Pesika, Conor		conor.pesicka@state.co.us	
James, Brian		bjames@hpres.com	<a href="#">All Inspections</a>
,		dnr_cogccenforcement@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
238228	WELL	SI	07/01/2017	GW	123-05061	SHOE 1	SI

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Weeds overgrown on access Rd.		
Corrective Action	Comply with Rule 603.f	Date:	11/21/2019

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	TB sign has old operator information. Form 10 was submitted on 5/1/2019 Doc.#402018972 and is in process.		
Corrective Action:	Comply with Rule 210.b	Date:	12/14/2019
Type	WELLHEAD		
Comment:	WH sign has old operator information. Form 10 was submitted on 5/1/2019 Doc.#402018972 and is in process.		
Corrective Action:	Comply with Rule 210.b	Date:	12/14/2019

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Weeds overgrown on entire location		
Corrective Action:	Comply with Rule 603.f	Date:	11/21/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Steel pipe		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barb wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Automation		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
	Date:			

**Venting:**

Yes/No	YES	
Comment:	Well appears to be venting along threads	
Corrective Action:	Comply with Rule 912.b 24 hrs. to repair or isolate the leak. Rule 605.d. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition.	Date: 11/15/2019

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 238228 Type: WELL API Number: 123-05061 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 11/25/2019 at approximately 1200 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at the Shoe #1KP Kauffman, at API # 05-123-05061 in Weld County Colorado.</p> <p>While there, I observed SI well and Tank battery. This is a follow up inspection per Doc. # 699300568</p> <p>During this inspection the following possible compliance issues were observed and are now delinquent:</p> <p>Rule 603.f Housekeeping: Dead weeds on access road, and throughout well site location. CA date 11/21/2019 see attaches photos #3, 4, and 5.</p> <p>605.d Mechanical conditions and 912.b Gas being vented or flared during non-upset condition: Wellhead appears to be venting around the threads to atmosphere. Securely fasten all valves,</p> <p>pipes and fittings to ensure good mechanical conditions inspect at regular intervals and maintain. 30 days unless leak is found then 24 hrs. To repair or isolate the leak. CA date 11/15/2019 See attached video.</p> <p>The following possible compliance issue is still within corrective action date and not considered delinquent.</p> <p>WH sign and TB sign still show Highpoint Resources and their emergency number. The form 10 was submitted on 5/1/2019 Doc. # 402018972 and is in process KP Kauffman should replace signs</p> <p>immediately so proper information is at wellsite See attached photo #1 and 2.</p> <p>Location is dry, weather is cloudy.</p> <p>At approximately 1210 hrs I spoke with Chris Ellis with KP Kauffman I explained that this is the second call about the WH venting gas around the threads and it is delinquent and according to COGCC Rule 912.b. he said he was going to send his operator that is in the area to take care of it. This inspection is being submitted to enforcement due to compliance issues not being addressed. At approximately 1315 hrs Chris Ellis called me back and said that his crew had made it out to the wellsite and fixed the venting issue. I will go back out and reinspect the wellhead to ensure venting has been stopped.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	11/25/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300632	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4998447">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4998447</a>
699300633	WH video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4998448">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4998448</a>