

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/26/2019

Submitted Date:

11/26/2019

Document Number:

689803390

FIELD INSPECTION FORM

Loc ID 313190 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 97810
Name of Operator: EOG Y RESOURCES INC
Address: 105 SOUTH 4TH ST
City: ARTESIA State: NM Zip: 88210

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Elgin, Jerry		jelgin@mspartners.com	
Gallenbeck, Danny		dgallenbeck@ctfieldsvcs.com	
Blaylock, Connie		cblaylock@mspartners.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271331	WELL	SI	12/29/2010	GW	081-07173	BAKERS PEAK UNIT 2	SI

General Comment:

MIT witness.

Inspected Facilities

Facility ID: 271331 Type: WELL API Number: 081-07173 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Inspector on location to witness MIT for continued shut in status. 880 psi on tubing and 0 psi on bradenhead to start test. Casing was presssured from tubing to 365 PSI and held for 15 minutes. 880 PSI on the tubing and 0 PSI on the bradenhead for the duration of the test.

Corrective Action: _____

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689803391	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4999009