

Inspection Photos

Location Name: COUNTRYMAN 24-31

API#: 05-071-09404

INSP. #: 695101824



Colorado Oil & Gas Conservation Commission
37.29671, -104.71803, 2182.0m, 100°
2019/11/25 14:41:54



Colorado Oil & Gas Conservation Commission
37.29678, -104.71763, 2191.0m, 15°
2019/11/25 14:42:15

PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: COUNTRYMAN 24-31

API#: 05-071-09404

INSP. #: 695101824



PHOTO 3: AREA OF IMPACTED SOIL NEAR PRIME MOVER (ENGINE SKID) MOTOR ON ENGINE SKID HAS OIL LEAKS IN NUMEROUS PLACES. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. Increase frequency of maintenance and self inspection schedule of equipment to prevent impacting surface materials and mixing of wastes with precipitation. Rule 907 & 1002.f.(2). CA DATE 12-25-19.

PHOTO 4: ANOTHER AREA OF IMPACTED SOIL AROUND COMPRESSOR. SAME CA AS PHOTO 3.

Inspection Photos

Location Name: COUNTRYMAN 24-31

API#: 05-071-09404

INSP. #: 695101824



PHOTO 5: ANOTHER AREA OF IMPACTED SOIL AROUND WELLHEAD. SAME CA AS PHOTO 3.



PHOTO 6: MECHANICAL CONDITION. HYDRAULIC HOSE LEAKING AT CONNECTIONS. Increase frequency of maintenance and self inspection schedule of equipment to prevent impacting surface materials and mixing of wastes with precipitation. Rule 907 & 1002.f.(2). CA DATE 12-25-19.