

Inspection Photos

API: 05-017-07811

Operator: MCCOY PETROLEUM CORPORATION

Inspection Date: 11/25/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07811 | Date: 11/25/2019

Inspection Photos



Photo 1. Northwest side of the location facing southeast. The location was in process of construction.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07811 | Date: 11/25/2019

Inspection Photos



Photo 2. Topsoil was stockpiled at the west side of the location. There did not appear to be enough topsoil salvaged at the time of inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07811 | Date: 11/25/2019

Inspection Photos



Photo 3. Southwest side of the location facing east. Surface roughening around the perimeter however this practice should be performed in conjunction with other BMP's.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07811 | Date: 11/25/2019

Inspection Photos



Photo 4. Facing east along the southern edge of the location which show topsoil salvaged was approximately 6 inches on this side of the pad and even less on the northern side of the pad.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07811 | Date: 11/25/2019

Inspection Photos



Photo 5. Location sign was posted at the center of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07811 | Date: 11/25/2019

Inspection Photos



Photo 6. The drilling pit had been excavated and topsoil was salvaged and stored in upper left of the photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07811 | Date: 11/25/2019

Inspection Photos



Photo 7. Excavated pit shows topsoil horizon.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07811 | Date: 11/25/2019