

Inspection Photos

API: 05-017-07255

Operator: KUENZLER & FLORA RESERVE COMPANY

Inspection Date: 11/25/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07255 | Date: 11/25/2019

Inspection Photos



Photo 1. Facing east along the access road to the location. The road has been widened and disturbed during drilling operations. Disturbance outside of the road must be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07255 | Date: 11/25/2019

Inspection Photos



Photo 2. Facing northeast toward the location. The location sign has fallen over and is not properly installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07255 | Date: 11/25/2019

Inspection Photos



Photo 3. The electric fence around the location is in disrepair and wire is strung along the ground.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07255 | Date: 11/25/2019

Inspection Photos



Photo 4. Facing toward the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07255 | Date: 11/25/2019

Inspection Photos



Photo 5. Drilling pit remains open and drilling materials present.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07255 | Date: 11/25/2019

Inspection Photos



Photo 6. The is a torn bag of unknown contents which is spilled on the ground.



Inspection Photos



Photo 7. Excavated pit remain open at the location. There are signs that cattle have been entering the pits.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07255 | Date: 11/25/2019

Inspection Photos



Photo 8. The lined pit remains open. The liner is torn and in disrepair.



Inspection Photos



Photo 9. Facing south at the location. Top soil was not properly salvaged from the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07255 | Date: 11/25/2019

Inspection Photos



Photo 10. There are minimal topsoil salvage piles at the southeast side of the location which are not protected.

