

Inspection Photos

API: 05-017-07809

Operator: MCCOY PETROLEUM CORPORATION

Inspection Date: 11/25/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07809 | Date: 11/25/2019

Inspection Photos



Photo 2. Topsoil is salvaged and stored at the south side of the location. Topsoil is tracked for temporary stabilization. Topsoil will need to be seeded and stabilized if reclamation is not performed soon.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07809 | Date: 11/25/2019

Inspection Photos



Photo 3. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07809 | Date: 11/25/2019

Inspection Photos



Photo 4. Facing north along the east side of the location. The side of the pad was tracked in however, soils are loose and susceptible to erosion. Surface roughening was performed around the perimeter but is inadequate to control erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07809 | Date: 11/25/2019

Inspection Photos



Photo 5. Facing south at the east side of the location. The side of the pad was tracked in however, soils are loose and susceptible to erosion. Surface roughening was performed around the perimeter but is inadequate to control erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07809 | Date: 11/25/2019

Inspection Photos



Photo 6. Facing west at the north side of the location. Topsoil appears to be salvaged and stored at this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07809 | Date: 11/25/2019

Inspection Photos



Photo 7. Facing northeast toward the drilling pits. Drilling material and fluid are present in the pits.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07809 | Date: 11/25/2019