

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/19/2019

Submitted Date:

11/21/2019

Document Number:

690101526

FIELD INSPECTION FORM
 Loc ID 320297 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10675

Name of Operator: DANMAR PRODUCTION COMPANY LLC

Address: 3945 18TH STREET LANE

City: GREELEY State: CO Zip: 80634

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Whittington, Ellice		ellice.whittington@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
BAKER, DANNY		dbaker57@comcast.net	DANMAR

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203389	WELL	SI	04/01/2016	OW	001-08898	CIMYOTTE 6-21	EG

General Comment:

COGCC Flowline Inspection Only. Photos Uploaded.

The Corrective Actions identified during this COGCC (EG) field inspection are located in the flowline section of report.

ALL CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Inspected FacilitiesFacility ID: 203389 Type: WELL API Number: 001-08898 Status: SI Insp. Status: EG**Flowline**

#1	Type:Non-Well Site	of Lines	
----	--------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment:

This well is currently shut in.
 The off location flowline (wellhead line) runs approximately 580' North from the wellhead to battery. This off location flowline has not been registered with COGCC; Operator has not submitted COGCC Form 44.

Note: Operator has not registered any off location flowlines with COGCC; Corrective Action outlined may be applicable to additional wells operated by Danmar Production Company.

Corrective Action:

Operator shall comply with the following COGCC rule:

1101.a. Off-Location Flowline Registration.
 (1) An operator must register an off-location flowline constructed on or after May 1, 2018, by submitting a Flowline Report, Form 44, to the Director within 30 days after the flowline is placed into service. An off-location flowline in existence prior to May 1, 2018, must be registered by October 31, 2019. An off-location flowline registered as part of a produced water transfer system is not subject to this requirement.

Date: 10/31/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402246274	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995135
690101547	Signage at tank battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995131
690101548	View south from facility/ battery to well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995132
690101549	View North from well to facility/ battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995133