

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/19/2019

Submitted Date:

11/21/2019

Document Number:

690101528

FIELD INSPECTION FORMLoc ID 319883 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 19035

Name of Operator: OVERLAND RESOURCES LLC

Address: SUITE C18 PMB 440

City: GREENWOOD State: CO Zip: 80121

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Whittington, Ellice		ellice.whittington@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Pandolfo, Chris		cpandolfo@gmail.com	
Behrens, Vic		behrens@netecin.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201765	WELL	SI	07/01/2017	OW	001-07169	ALLISON, NORA 1	SI

General Comment:

COGCC Flowline Inspection Only. Photos Uploaded.

The Corrective Actions identified during this COGCC (EG) field inspection are located in the flowline section of report.

ALL CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Inspected Facilities

Facility ID: 201765 Type: WELL API Number: 001-07169 Status: SI Insp. Status: SI

Flowline

#1	Type:Non-Well Site	of Lines	
----	--------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: This well is currently shut in.

The off location flowline (wellhead line) runs approximately 560' S-SW from the wellhead to battery. This off location flowline has not been registered with COGCC; Operator has not submitted COGCC Form 44.

Note: Operator has not registered any off location flowlines with COGCC; Corrective Action outlined may be applicable to additional wells operated by Overland Resources.

Corrective Action: Operator shall comply with the following COGCC rule:

1101.a. Off-Location Flowline Registration.

(1) An operator must register an off-location flowline constructed on or after May 1, 2018, by submitting a Flowline Report, Form 44, to the Director within 30 days after the flowline is placed into service. An off-location flowline in existence prior to May 1, 2018, must be registered by October 31, 2019. An off-location flowline registered as part of a produced water transfer system is not subject to this requirement.

Date: 10/31/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402246038	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4994832
690101541	Signage; View east from tank battery to wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4994821
690101542	View west from wellhead to facility/ battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4994822