

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/19/2019

Submitted Date:

11/21/2019

Document Number:

690101530

FIELD INSPECTION FORM

Loc ID 320187 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 70350
Name of Operator: PILAND RESOURCES
Address: 43651 E 38TH AVE
City: BENNETT State: CO Zip: 80102

Findings:

- 3 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Whittington, Ellice		ellice.whittington@state.co.us	
Piland, Sarah		sarahpiland@hotmail.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202952	WELL	PR	04/12/2004	GW	001-08357	PILAND 15-3	EG

General Comment:

COGCC Flowline Inspection Only. Photos Uploaded.
The Corrective Actions identified during this COGCC (EG) field inspection are located in the flowline and housekeeping sections of report.
Note: The corrective actions outlined on COGCC FIR Doc #688401486 submitted on 03/12/2019 are still applicable.
ALL CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Note: (4) Inactive flowline risers observed at facility/ battery in area of heated horizontal separator; risers have been bullplugged, not LOTO.		
Corrective Action:	Comply with COGCC rule 603.f. Inactive flowline risers are unused equipment; Per COGCC rule 603.f. For unused unmarked flowline risers 24hrs to lock out/ tag out; 30 days to remove unused (inactive) flowline risers.		Date: <u>12/23/2019</u>

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 202952 Type: WELL API Number: 001-08357 Status: PR Insp. Status: EG**Flowline**

#1	Type: Non-Well Site	of Lines
<u>Flowline Description</u>		
Flowline Type: <u>Non-Well Site</u>	Size:	Material:
Variance:	Age:	Contents:
<u>Integrity Summary</u>		
Failures:	Spills:	Repairs Made:
Coatings:	H2S:	Cathodic Protection:
<u>Pressure Testing</u>		
Witnessed:	Test Result:	Charted:
<u>COGCC Rules (check all that apply)</u>		
<input type="checkbox"/> 1101. Installation and Reclamation <input checked="" type="checkbox"/> 1102. Operations, Maintenance, and Repair <input type="checkbox"/> 1103. Abandonment		
<u>Comment:</u>	This well is currently shut in. The off location flowline (wellhead line) runs approximately 1720' NE from the wellhead to battery. This off location flowline has not been registered with COGCC; Operator has not submitted COGCC Form 44. Note: Operator has not registered any off location flowlines with COGCC; Corrective Action outlined may be applicable to additional wells operated by Piland Resources.	
<u>Corrective Action:</u>	Operator shall comply with the following COGCC rule: 1101.a. Off-Location Flowline Registration. (1) An operator must register an off-location flowline constructed on or after May 1, 2018, by submitting a Flowline Report, Form 44, to the Director within 30 days after the flowline is placed into service. An off-location flowline in existence prior to May 1, 2018, must be registered by October 31, 2019. An off-location flowline registered as part of a produced water transfer system is not subject to this requirement.	
	Date: <u>10/31/2019</u>	

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402246189	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995062
690101543	Signage at wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995058
690101544	View NE from wellhead to facility/ battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995059
690101545	View SW from battery to wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995060
690101546	Inactive/ unused flowline risers	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995061