

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/21/2019

Submitted Date:

11/22/2019

Document Number:

699700048**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Heil, John _____ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10442Name of Operator: HUNTER RIDGE ENERGY SERVICES LLCAddress: 370 17TH STREET #1700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Arauzo, Steven		steven.arauza@state.co.us	
Buck, Paul		paul.buck@encana.com	
Henry, Jen		Jennifer.Henry@encana.com	A27

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
468839	SPILL OR RELEASE	AC	10/24/2019		-	A27 12" poly line	EI

General Comment:

On October 21 and October 31, 2019, COGCC Environmental Staff (John Heil and Steven Arauzo) conducted an environmental field inspection of HUNTER RIDGE ENERGY SERVICES LLC (Operator #10442) Spill ID 468839. See attached summary for details.

Location

Lease Road:			
Type	Access		
comment:	Operator's truck blocking access to the northern section of the location.		
Corrective Action	Comply with rule 204.	Date:	12/22/2019

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date: _____
Corrective Action:		

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil with a detectable hydrocarbon odor located north of the Water Collection Vault.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	12/04/2019

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment: Secondary containment of the pump generator in disrepair.				
Corrective Action: Install liner material to ensure spill or released materials will be maintained with containment structure.				Date: 12/22/2019

Venting:

Yes/No		
Comment:		

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 468839 Type: SPILL OR API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402246659	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995736
699700053	20191021, 31 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995734
699700054	20191021, 31 Summary	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4995735