

Inspection Photos

API: 05-025-06020

Operator: CRAZY 8 ENERGY LLC

Inspection Date: 11/25/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-025-06020 | Date: 11/25/2019

Inspection Photos



Photo 1. Facing northwest toward the location. The location has not been recontoured. Soil piles and ditches remain.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 11/25/2019

Inspection Photos



Photo 2. Facing north toward the location. The location has not been reclaimed. There are weeds and bare soil throughout the site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 11/25/2019

Inspection Photos



Photo 3. The pit area has been closed and backfilled however, soils have not been leveled and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 11/25/2019

Inspection Photos



Photo 4. There is a pile of pit liner debris that remains at the east side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 11/25/2019

Inspection Photos



Photo 5. Facing south toward the location. There is undesirable weeds (*Kochia* sp.) throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 11/25/2019

Inspection Photos



Photo 6. The diversion ditches around and through the location have not been backfilled and reclaimed. There are erosion issues along the ditches.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 11/25/2019

Inspection Photos



Photo 7. Facing southeast toward the pit area. The pit area has been closed and backfilled however, soils have not been leveled and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 11/25/2019

Inspection Photos



Photo 8. Facing north toward outside of the location the land use is cropland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 11/25/2019

Inspection Photos



Photo 9. Facing west toward outside of the location the land use is cropland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 11/25/2019

Inspection Photos



Photo 10. Facing east toward outside of the location the land use is cropland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-025-06020 | Date: 11/25/2019